


Bandisholai Panchayat – Status of water sources

S No.	Item	Number
1	Total Number of habitations	5
2	No. of habitations surveyed	5
3	Total number of households	198
4	Number of households surveyed % of households surveyed	62 33%
5	Households harvesting rain water at home	10
6	Average water storage capacity in a household (in liters)	283
7	% of households with storage capacity of 1000 liters or less	100%
8	% of households with storage capacity of 500 liters or less	83%
9	% of households with storage capacity of 250 liters or less	69%
10	Average water consumption per family (liters per day) Maximum	688 2040
11	Number of habitations with only spring water supply	3
12	Number of habitations with spring and well water supply	2
13	% of Households practicing Open Defecation	33%
14	Number of habitations reporting Open Defecation % of habitations reporting Open Defecation	4
15	Number of habitations with Community Toilets	1
16	Number of habitations reporting usage of Community Toilets	1
17	Number of habitations reporting collection of waste at the doorstep	Nil
18	Number of habitations reporting waste bins being located	2
19	% of households reporting purchase of water	Nil
20	% of households reporting water borne diseases	5% (All from Soladamattam)

Water use pattern

Percentage share of various uses on average in BerhattyPanchayat



Water Supply Situation

S No.	Habitation Name	Sources	Source Type(s)	Supply	Issues reported in surveys
841	Mallanur	Estate CMS Mallanur Village	Spring Stream Spring Well	Daily supply. Adequate from all sources.	-
842	Melsingara	5 No. valley 8 No. Guerency	Spring Spring Stream	Daily supply throughout the year	Less in Summer from all sources
843	Govt seed farm	UPASI Forest	Stream Stream	Daily Supply throughout the year	Less in Summer from all sources
844	Nanjapachatram	Govt. Seed Farm Forest	Stream Stream	Daily Supply throughout the year	Less in Summer from Seed Farm Spring.
845	Sholadamattam	Forest - 2 Muneeswaran kovil`	Spring Spring	Daily Supply throughout the year	

Water Quality Issues

S No.	Habitation Name	Sources	Source Type(s)	Problem
841	Mallanur	Estate CMS Mallanur Village	Spring Stream Spring Well	Water quality issues
842	Melsingara	5 No. valley 8 No. Guerency	Spring Spring Stream	-
843	Govt seed farm	UPASI Forest	Stream Stream	-
844	Nanjapachatram	Govt. Seed Farm Forest	Stream Stream	Source dirty. Water quality issues.
845	Sholadamattam	Forest - 2 Muneeswaran kovil	Spring Spring	Water quality issues.

Habitations where Community Toilets are present and being used

Habitation id	Habitation name	Community Toilet Present	Community Toilet in use
841	Mallanur	No	No
842	Melsingara	Yes	Yes
843	Govt seed farm	No	No
844	Nanjapachatram	No	No
845	Sholadamattam	No	No
	No. of habitations	1	1

Habitations where Open Defecation is being practised

Habitation ID	Habitation Name	HHs reporting OD	Surveyed HHs	% reporting OD
841	Mallanur	0	10	0
842	Melsingara	1	10	10

Habitation ID	Habitation Name	HHs reporting OD	Surveyed HHs	% reporting OD
843	Govt seed farm	2	12	16
844	Nanjapachatram	6	10	60
845	Sholadamattam	11	20	55
		20	62	32%
	No. of habitations	4	5	80%

Status of Waste Management

Habitation ID	Habitation Name	Waste Collection at Door Step	Waste bins setup by Panchayat
841	Mallanur	No	Yes
842	Melsingara	No	No
843	Govt seed farm	No	No
844	Nanjapachatram	No	No
845	Sholadamattam	No	Yes
	No. of habitations	0	0